



IPD TECH BULLETIN


Lower Cylinder Block Bores for 3400, C15, & C18 engines

An area on the cylinder block that too often gets overlooked during overhauls is the lower receiver bore area that supports the bottom of the cylinder liner. The wear in the photo below is an example of the damage that can result on a worn cylinder block. The cylinder block needs to be repaired prior to installing a new cylinder liner.



With newer engines developing higher cylinder pressures & horsepower, and older engines possibly having been overhauled a few times already, making sure the liner is properly supported is even more important. Some engines are being upgraded from an older aluminum piston to the newer steel piston designs and this can increase the demand for performance of cylinder components as well. Clearances in the newer technology steel pistons are much tighter than those of their older aluminum predecessors, so controlling the liner movement could head off an expensive failure.

The process to repair the lower receiver bore is done with a “step” bore machining technique and a 4W6061 lower repair sleeve. To do this the cylinder block is machined to a specific oversized diameter and to a specific depth to create the proper press fit and a step in the block bore. The “Step”, as shown below helps retain the sleeve and creates a good seal when the sleeve bottoms out against it.



The oversized dimensions to be machined into the cylinder block (shown above) to accept the 4W6061 repair sleeve and create the proper press fit are:

Depth of machining is 8.826 +/- .010” (224.19 +/- 0.25mm)

Diameter is 6.2205 +/- .001” (158.00 +/- 0.025mm)

IPD
Torrance CA USA 90501
www.ipdparts.com

IPD is an ISO9001:2000 Certified Company

All information is believed to be accurate at time of printing. No guarantee of accuracy is made by IPD llc. Please consult your service and parts manual for detailed information. This is intended as a warning only, not a specification.

All manufacturers' names, numbers, symbols and descriptions are for reference only. It is not implied that any part is the product of the manufacturer. Caterpillar ® and Cat® are registered trademarks of Caterpillar, Inc

To install the repair sleeve the block and sleeve must be clean and dry. Apply high strength Loctite® to the block and freeze the repair sleeve. Install the sleeve with the ID taper upward and hold in place until seated. Allow adequate time for the Loctite® to dry before finish machining.

Finish machining the ID of the installed repair sleeve to 6.059 +/- .002” (153.90 +/- 0.05mm)

As engines evolve and components improve it is always best to use the latest specifications and technical information before beginning the machining processes. These instructions and dimensions are the most current available as of this printing.

On 3400 & C15 series engines you might also consider installing IPD’s unique “Crevice Seal” liner to help reduce liner movement. Contact IPD for more information concerning these liners or visit www.ipdparts.com.

IPD

Torrance CA USA 90501

www.ipdparts.com

IPD is an ISO9001:2000 Certified Company

All information is believed to be accurate at time of printing. No guarantee of accuracy is made by IPD llc. Please consult your service and parts manual for detailed information. This is intended as a warning only, not a specification.

All manufacturers' names, numbers, symbols and descriptions are for reference only. It is not implied that any part is the product of the manufacturer. Caterpillar ® and Cat® are registered trademarks of Caterpillar, Inc