


Another Surprise Inside Cummins ISX


BY STEVE SCOTT

When we put the final wrap on the “Surprise Inside Cummins ISX” article in the July-Sept 2021 issue, I thought we had covered the topics of most interest. I wasn’t too surprised to hear that not only did we miss a key topic, but the OE seems to have overlooked it completely. The OE service manuals do a good job of detailing the acceptable conditions and dimensions for the lower counterbore in the ISX cylinder block and the required liner protrusion specs. However, it falls far short of addressing wear on the upper receiver bore of the block that supports the top of the liner. The only reference I have found is the simple note (shown below) taken from Cummins “Inspect for Reuse” guide that focuses on erosion. However, erosion and wear are completely different conditions.

If upper bore erosion is discovered during block inspection, it **must** be disregarded. It is **not** a failure mode and the head gasket provides an adequate seal.



The problem occurs when the upper bore diameter of the block gets worn to the point it cannot hold the liner from moving. The liner movement then causes the head gasket to fret into the surface of the cylinder head and the head gasket to fail.




At the time the OE guide was published, had they not considered the wear these engines would experience? Especially as they age, and the engine experiences the countless number of miles put on these blocks. Pictured far right, these four photos are examples of the wear found around the circumference in the upper receiver bores of a high mileage ISX block.

The upper landing of the cylinder liner is fairly narrow in comparison to



Examples of wear found around the circumference in the upper receiver bores of a high mileage ISX block.





the mating area of the cylinder block. Since the cylinder liner is a “mid-stop” design, it is held at the lower counter bore and at the top by the head gasket.


The photos shown here are from an ISX engine that failed the head gasket on two cylinders. There was also fretting damage to the cylinder head on all six cylinders.

Pictured below is a rough outline of the construction of the head gasket. At each of the cylinders there is a fire wire, or ring incased by the fire wrap. The crushing force from the cylinder head seals this area of the head gasket to the liner.

When the cylinder liner is not held firmly in place at the top by the cylinder block the liner begins to move with each stroke of the engine. This causes the gasket to fret into the cylinder head, cracking the fire wrap on the head gasket and the gasket soon fails. This is not the gasket’s fault – it has scrubbed against the cylinder head to the point it fails. The clamping force from the cylinder head pushes downward to the lower counter bore in the block and



Rough outline of the construction of the head gasket. At each of the cylinders there is a fire wire, or ring incased by the fire wrap. The crushing force from the cylinder head seals this area of the head gasket to the liner.



CUMMINS ISX

BY STEVE SCOTT



the top of the liner dances around. The gasket is not designed to withstand this type of movement or force.

I have talked to several machine shops and rebuilders about this condition since the last article and have been told this is becoming a more common occurrence. If severe enough, it requires a custom sleeve or insert to be installed in the block to repair the damaged area. When they install a repair sleeve in the block, the rebuilders tend to use a finish bore size of 6.339" to 6.340". Cummins lists a max spec diameter of 6.340" for this upper area of

the liner, but do not publish a spec of the block upper bore diameter. Possibly the movement of the liner or the wear may be seen while the liner is still in the block, but to get an accurate measurement the liners would need to be removed. Without a published spec the acceptable amount of clearance or wear is unknown. A worn diameter of 6.344" tends to be the max diameter for the block according to the rebuilders I spoke with.

In some ways I was hesitant to publish this article because I do not have an out of the box solution. Without documented

specs or procedures for repairing the block damage, the best I have to offer is pointing out a possible problem. Hopefully this information will be useful and fend off a potential failure. With the age, popularity, and huge number of these ISX engines in production, there is no doubt there will be more surprises to come in the ISX crackerjack box. ■



Steve Scott joined the service department at IPD in 1982, working with parts, service and sales for a variety of equipment, diesel, and natural gas engines. Since 2004, he has been the director of product development and technical support for IPD. For more information, email sscott@ipdparts.com.



QUALITY ENGINE REPLACEMENT PARTS FOR INDUSTRIAL AND POWER GENERATION



- Engine rebuild kits
- Piston kits
- Bearings, gasket sets and ring sets
- Head bolt kits
- Lower-end gasket kit
- Oil pan gaskets and seals

IPD HEADQUARTERS
23231 Normandie Ave.
Torrance, CA 90501 310.530.1900
sales@ipdparts.com



All manufacturers' names, numbers, symbols and descriptions are for reference only. It is not implied that any part is the product of the manufacturer. Caterpillar®, Detroit Diesel®, Cummins® and Waukesha® are registered trademarks of their respected owners.



IPD Products for Diesel and Spark-Ignited Engines	
Caterpillar®	C6, C7, C9, C10, C11, C12, C13, C15, C18, C27, C32, 300 Series, 3000, 3100, 3200, 3300, 3400, 3500, 3600
Cummins®	ISX / QSX (dual cam), ISX15 / QSX15 (single cam), and K Series (19L, 38L, 50L)
Detroit Diesel®	60 Series and DD15 Series
Waukesha®	VHP Series (7042/7044)

ipdparts.com

ISO 9001: 2015 Certified